

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940 JAN 2 2 2001

DIVISION OF
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Gene	eral Information					
	1.	Report Time Period: From (mo./yr.) 1/2000 To (mo./yr.) 12/2000					
	2.	DOGM File Number (Mine No): M / 045/037					
	3.	Mine Name: Morton Salt/Grantsville					
	4.	Mineral(s) Mined (or permitted to mine): Salt (Sodium Chloride)					
	5.	Type of mine					
	6.	Legal Description (Location of Lands Affected): See Attached					
		1/4,1/4,1/4, Section, Township, Range					
		1/4,1/4,1/4, Section, Township, Range					
		1/4,1/4,1/4, Section, Township, Range					
7.	Nam	e of Operator or Company: Morton Salt					
	8.	Permanent Street Address: I-80 West Exit 84 (P.O. Box 506)					
		City, State, Zip: Grantsville, UT 84029					
		Phone: 801-250-6335 Fax: 801-933-4410					
	9.	Company Representative (or designated operator):					
		Name:JAMES H. HUIZINGH					
		Title:Facility Manager					
		Business Address: P.O. Box 506 (I-80 West Exit 84)					
		City, State, Zip: Grantsville, UT 84029					
		Phone: 801-250-6335 Fax: 801-933-4410					
		☐ Please check if any of the above information has changed since previous year.					
II.	Mining and Reclamation						
	1.	Was there any mine related activity during the past year? Yes ☑ No □					
	2.	If no - what was the last year of activity?					
	3.	If yes - how much ore or mineral was mined? 616,359 Tons					

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.							
	Repair and maintenance of existing dykes.							
5.	How much additional acreage was dist	urbed during the past year?0						
6.	How much acreage was reclaimed during the past year?0							
7.	Briefly describe the reclamation work poshould include methods employed, and a	erformed during the past year. This description an evaluation of the results.						
8.	What is the total disturbed acreage of entire project at years end? 15,000 acres							
9.	9. Briefly summarize any mining and/or reclamation plans for the upcoming year. We anticipate harvest of the same pond acreage annually.							
NOTE:	Section III., "Additional Information" ap	oplies only to large mining operations.						
III. Additional	<u>Information</u>							
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.							
2.	2. Any monitoring results or other reports that are required under the terms of the approve intention should also be attached.							
IV. <u>Signature</u>	<u>Requirement</u>							
I here	by certify that the foregoing is true	and correct.						
	Name (Typed or Print):	JAMES H. HUIZINGH						
	Title of Operator:	Facility Manager						
	Signature of Operator:	James H. Hairings						
	Date:	1/18/01						
jb a:\forms\MR-AR								

LOCATION OF OPERATION:

County:	Tooele						
Township:	1N	Range:	5W	Section(s):	19		
Township:	1N	Range:	6W	Section(s):	24, 25, 26, 32, 33, 34, 35		
Township:	1S	Range:	5W	Section(s):	16, 19, 20, 21		
Township:	1S	Range:	7W	Section(s):	1, 2, 3, 10, 11, 12, 13, 14, 15		
Township:	1S	Range:	6W	Section(s):	2, 3, 4, 5, 6, 7, 8, 9, 10, 11,		
-		•			13, 14, 15, 16, 17, 18, 19, 20,		

21, 22, 23, 24, 25, 26, 27, 28, 29